CAUTION

DAMAGE TO UPPER BALL GATE MAY OCCUR WHEN
LIFTING AND/OR LOWERING PLAYFIELD

STD-638

INSTALL 3 BALLS

INSTALL 4 BALLS

INSTALL 5 BALLS

INSTALL 6 BALLS